


## Seismic Vulnerability Map (4)





### Seismic intensity in Mitoyo City



### Safety measures inside the house

### •Fall prevention of furniture

Fix tall furniture with L-shaped brackets. Since two-tiered or stacked furniture is particularly prone to fall, connect with flat fittings.

Apply a tension pole between the ceiling and furniture. Insert a fall prevention plate, etc. under furniture and fix it so that it rests on the wall and pillar.

### Safe furniture layout

When placing furniture in a sleeping room, arrange it so that it will not fall on your body.

### Window panes

Check them for cracks and loose window frames, and attach glass protective films or rain door.



# 13/13

### Safety measures outside the house

### Fences

Do the concrete block fences and gateposts contain reinforcing steel properly?

Is the foundation robust If there is any crack or leaning, repair it.

### Roofs

Aren't there any crack, displacement, peeling, etc.?

Fix the antenna securely.

### Outside walls

Isn't there any crack, corrosion or floating? Repair it, if any.

### Propane gas

Place the gas cylinder on a solid foundation. Fix the cylinder to the wall surface with chains, etc.

